



## Xplore Technologies Software Release Note

|                            |                                     |
|----------------------------|-------------------------------------|
| Name                       | <b>Intel Bluetooth Driver</b>       |
| File Name                  | <b>Bluetooth_18.1.1546.2762.zip</b> |
| Release Date               | May 9, 2016                         |
| This Version               | 18.1.1546.2762                      |
| Replaces Version           | All previous versions               |
| Intended Product           | iX101B1 (Bobcat)                    |
| File Size                  | 8.3 MB                              |
| Supported Operating System | Windows 8.1                         |

### Fixes in this Release

- BT headphone/headset fails to auto-reconnect or takes too long after reboot (S5) or after Sx cycles
- Can't send file via Bluetooth after Cold boot

### What's New in this Release

- N/A

### Known Issues and Limitations

- N/A

### Installation and Configuration Instructions

**To install Bluetooth 18.1.1546.2762, perform the following steps:**

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (setup.exe) and follow the prompts.

### Licensing

Refer to your applicable end-user licensing agreement for usage terms.