

Release Notes – MPA3.0 – SHA2 Support for all MPA3.0 Products - SPR 26391

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

This patch addresses SPR26391 – MPA3.0 – SHA2 Support for all MPA3.0 Products. As part of fix, Microsoft released a new AKU 6.5.3.12.35 (build no. 29299) which contains the support for recognizing the SHA2 certificate through Cryptographic APIs (CAPIs).

Description

- 1) This issue is seen on all MPA3.0 devices running WEHH6.5. SHA2 certificate is not recognized properly and installing any root SHA2 certificate gets installed in intermediate section rather than root section. Also there was an issue syncing emails from Microsoft exchange server.
- 2) The latest OS hotfix image built with AKU35 solves the issue.

Contents

67NAw65HenUL604640_Final.zip

92N0w65LenUL604602_WW.zip

92N0w65LenUL614602_LC.zip

92N0w65LenUL624602_Korgar.zip

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC67NA	Windows Mobile 6.5
MC92N WW	Windows Mobile 6.5
MC92N LC	Windows Mobile 6.5
MC92N Korgar	Windows Mobile 6.5

Installation Requirements

- MC67NA BSP 03.46.39 or earlier
- MC92N WW BSP 02.46.01 or earlier
- MC92N LC BSP 12.46.01 or earlier
- MC92N Korgar 42.46.01 or earlier

Installation Instructions

For NORMAL installation of the OS Hotfix image:

1. Unzip and copy the content to either \Temp or \Storage Card of the device.
2. Start the OS update by clicking the StartUpdLdr.exe file.
3. StartUpdLdr.exe will update the OS image and device will automatically coldboot.

Part Number and Release Date

67NAw65HenUL604640_Final.zip

92N0w65LenUL604602_WW.zip

92N0w65LenUL614602_LC.zip

92N0w65LenUL624602_Korgar.zip

November 25, 2014