

Release Notes - TC55 JB – BSP v01.74.00 - Device does not scan (No beam) after wake up from suspend – SPR27026

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

Device connected to BT printer does not scan (No beam) barcode on reboot followed by suspend and then wakeup.

Description

The new scanning framework 3.1.12 fixes the issue. The below package contains fix for the issue.

Contents

SPR270276_TC55_JB_en_1.74.00_v1.0.zip - fix package

Device Compatibility

This software release has been approved for use with the following Zebra devices.

Device	Operating System
TC55	Android 4.1.2 JB

Installation Requirements

This SW is intended for the TC55 device running non-GMS/GMS 01.74.00 JB build only.

Installation Instructions

OS Recovery Update:

1. Connect the USB cable from your PC to the device and enable USB mass storage mode on the device.
2. On your PC you should see an internal and external USB mass storage drive (SD card) appears in the File Explorer and copy the recovery update zip file to any storage.
3. Press and hold on the device the Power button, Scan/Action button and Vol+ button until the screen is turned OFF.
4. Release the Power and Scan/Action buttons and continue to hold Vol+ button.
5. The device should enter to Recovery update mode.
6. Release Vol+.
7. Click on Vol+ or Vol- to navigate and select appropriated storage.
8. Click on Scan/Action button to select the option.
9. Click on Vol+ or Vol- to navigate to the recovery update zip file.
10. Click Scan/Action button to select the recovery update zip file.
11. Device will automatically reboot and will be ready to use.

Part Number and Release Date

NA

April, 2015