XPLORE
TECHNOLOGIES

Motion Computing Software Release Note

Name	**SnapWorks by Motion**
File Name	**SnapWorks_1.0.5141.27153_Licensed.zip**
Release Date	February 3, 2014
This Version	1.0.5141.27153
Replaces Version	All previous versions
Intended Users	**Motion Computing Tablet PC users**
Intended Product	CL900, CL910, J3500, J3600, C5v/F5v, C5t/F5t Tablet PCs only
Supported Operating System	Windows 8 (32-bit/64-bit) Windows 7 (32-bit/64-bit)

Fixes in this Release

- Viewfinder doesn't show full area of capture.
- Web camera displays image upside down when the device is rotated.
- PnP ID for camera configuration.
- Picture not mirrored on front camera.
- Corrupted photos in portrait orientation.
- Default to rear camera on startup only.
- Improved camera flash control.
- User can lose opportunity to add Time/ GPS stamp.
- Low resolution images do not expand to fill available screen resolution.

What's New in this Release

- N/A

Known Issues and Limitations

- Annotations do not scale properly during crop or orientation changes.
- Intermittent rotation anomalies under stress conditions.
- CL900 series will occasionally capture a black image.

Installation and Configuration Instructions

To manually install SnapWorks 1.0.5141.27153, perform the following steps:
1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Uninstall previous version of SnapWorks prior to installation.
4. Double-click the installer (SnapWorks.msi) and follow the prompts.
5. To configure your platform camera button copy the appropriate registry file to your desktop and double click on it.

To silently install SnapWorks 1.0.5141.27153 perform the following steps:
1. Run a command shell as Administrator.
2. Navigate to the directory you placed the SnapWorks msi installer and registry edit files.
6. Run the command SnapWorks.msi /qb LICENSEFILE=<path>\SnapWorks.lic

Licensing

Refer to your applicable end-user licensing agreement for usage terms.