XPLORE TECHNOLOGIES

Motion Computing Software Release Note

Name	**Sierra Wireless Skylight Connection Manager for Windows 8.1**
File Name	**Sierra_Wireless_Skylight_6.0.4106.7805.zip**
Release Date	August 12, 2014
This Version	6.0.4106.7805 (B4106)
Replaces Version	All previous versions
Intended Users	**Motion C5v/F5v, C5t/F5t, C5te/F5te, CL900, J3500 and J3600 users**
Intended Product	Motion C5v/F5v, C5t/F5t, C5te/F5te, CL900, J3500 and J3600 Tablet PCs ONLY
File Size	27 MB
Supported Operating System	Windows 8.1 (32-64-bit)

Fixes in this Release

- Fixed profile password issues
- Fixed occasional profile update error

What's New In This Release

- None

Known Issues and Limitations

- None

Installation and Configuration Instructions

To install Skylight Connection Manager, perform the following steps:
1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (.msi) and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.