Release Notes - *MC67 Android Jellybean Patch for eCompass Sensor AMI306M*

Introduction

This Package includes support for AMI306M ECOMPASS.

Description

AMI306M-MC67N0-J-00-X06116-N-00-01.zip – Contains patch update for AMI306M ECOMPASS support

Contents

AMI306M-MC67N0-J-00-X06116-N-00-01.zip - AMI306M ECOMPASS PATCH

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System	BSP Version
MC67	JellyBean 4.1.1	V06116

Installation Requirements

This SW is intended for the MC67 JB device.

Installation Instructions

1. Copy update AMI306M-MC67N0-J-00-X06116-N-00-01.zip to the root directory of SD card.
2. Place the SD card in the device to be upgraded and connect to A/C power.
3. Press and hold the Power button on the device until the Device options menu appears.
4. Tap on Reset to reboot the device.
5. When the device is rebooting hold the right Action button to enter Recovery update mode.
6. When the Recovery Mode screen appears release the Right Action button.
7. Tap Home Key to access recovery menu screen.
8. Tap Vol+, Vol- keys to navigate to apply update from /sdcard option.
9. Tap Enter to select this option.
10. Tap Vol+, Vol- keys to navigate to the update zip file.
11. Tap Enter to select this option.
12. After pressing Enter, the upgrade will start.
13. After upgrading successfully, the screen will back to Recovery mode menu.
14. Tap Vol+, Vol- keys to navigate to the reboot system now option.
15. Tap Enter to select this option.
16. After pressing Enter system will reboot.

Part Number and Release Date

67N0J06116-AMI306M

March 28, 2017