

Release Notes – SPR 25328 – TC55- After activating APPLockAdministrator, the Left trigger button stops working

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

SPR 25328 – TC55- After activating APPLockAdministrator, the Left trigger button stops working

Description

This patch fixes the problem which occurs after activating APPLockAdministrator and left trigger button stops working.

Contents

AppLockSystemApplications.zip

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
TC55	Android

Installation Requirements

n/a

Installation Instructions

1. Copy AppLockSystemApplications.zip file to SD card
2. Install AppLockSystemApplications.zip file by double click on it.
3. Reboot TC55 device

Part Number and Release Date

n/a

March, 2014.