

Motion Computing Software Release Note

Name	Sierra Wireless MC8355 (Gobi3000) Driver Package
Release Date	December 13, 2013
This Version	2.17.1302.0
Replaces Version	All previous versions
Intended Users	C5te/F5te users
Intended Product	C5te/F5te Tablet PCs ONLY
File Size	67 MB
Supported Operating System	Windows 8 (32-bit/64-bit)

Fixes in this Release

• Initial release

What's New in this Release

Initial release

Known Issues and Limitations

None

Installation and Configuration Instructions

To install MC8355 (Gobi3000) 2.17.1302.0, perform the following steps:

- 1. Click **download** to save the **MC8355 DriverPkg** to the directory of your choice.
- 2. **Unzip** the file to a location on your local drive.
- 3. Double-click **Setup.exe** and follow the prompts

Licensing

Refer to your applicable end-user licensing agreement for usage terms.