



## Motion Computing Software Release Note

Name	<b>Intel Wireless LAN Driver for Windows 8</b>
File Name	<b>Intel_WiFi_Win8_v17.16.0.zip</b>
Release Date	March 28, 2019
This Version	17.16.0
Replaces Version	All previous versions
Intended Users	<b>Motion Computing CL910 users</b>
Intended Product	Motion Computing CL910
File Size	93 MB (32-bit)
Supported Operating System	Windows 8 32-bit

### Fixes in this Release

- Adhoc connect following power management event
- Mixed Mode Protection
- BSOD during power management events and WHCK test
- Intermittent Wi-Fi icon "x" after resume from Sleep
- Slow to connect after resume from Sleep
- Rx performance
- Unable to disable wireless after resume from Sleep

### What's New In This Release

- 

### Known Issues and Limitations

- None

### Installation and Configuration Instructions

**To install WiFi 17.16.0 drivers, perform the following steps:**

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (.exe) and follow the prompts.

## Licensing

Refer to your applicable end-user licensing agreement for usage terms.