

Release Notes - Zebra ET55 Android M LifeGuard Update 08 WWAN (Non-GMS)

Highlights

This release contains the following software package which is compatible with the ET55 Non-GMS LifeGuard patches are cumulative and include all previous fixes that are part of earlier patch releases.

Software Packages

Package Name	Package Description
CFE-ET55-M-XX-032120-N-00-08.zip	CFE package update

Security Updates:

- Android Security Patch Level: 2018-08-05 (Critical Patch Level: 2021-02-01)

Use the below link to see the Android Security bulletin for more information:
<https://source.android.com/security/bulletin/>

1. CFE v8 Updates:

CFE-ET55-M-XX-032120-N-00-08.zip (Non-GMS)

- Updated Components:
 - WebView - 87.0.4280.141

2. CFE v7 Updates:

CFE-ET55-M-XX-032120-N-00-07.zip (Non-GMS)

- SPR40628 - Fixed the issue of GTK rotation failure in device due to invalid rates sent in TSPEC from the AP
- SPR40178 - Fixed the issue where sometimes device not responding to pings when in suspend state
- SPR39491 - Fixed the issue where device sends RIC IE in reassociation though AP is not supporting RIC
- SPR40705 - Fixed the device behavior to ignore the deauth/disassoc from previously connected AP

- Updated Components:
 - WebView 85.0.4183.127

3. CFE v6 Updates:

CFE-ET55-M-XX-032120-N-00-06.zip (Non-GMS)

- SPR39621 - Fixed an issue wherein UI manager CSP was crashed while setting EKB as default.
- SPR39572 - Resolved an issue wherein sim Card was not detected in earlier modems sporadically.
- Enable DataWedge Camera Decode and support multi-decode unique continuous mode.
- Updated Components:
 - WebView 83.0.4103.106

4. CFE v5 Updates:

CFE-ET55-M-XX-032120-N-00-05.zip (Non-GMS)

- SPR38483 - Resolved an issue where Bluetooth slowness seen with printer operation.
- SPR37841 - Cypress fixed the issue with power save which made the device not to receive the buffered packets.
- SPR38958 - Resolved an issue where VPN and ethernet connection was not using Domain name.
- SPR37982 - Resolved an issue wherein incorrect power consumption was reported against Bluetooth module
- SPR37434 - Resolved an issue wherein High CPU utilization is observed when StageNow is used to configure Fusion Advance logs.
- Updated the firmware for fixing Kr00k vulnerability issue seen with Broadcom Wi-Fi chipsets
-
- Updated components:
 - WebView 84.0.4117.0
 - FUSION_BA_3_10.0.5.014_M



5. CFE v4 Updates:

CFE-ET55-M-XX-032120-N-00-04.zip (Non-GMS)

- Updated components:
 - Webview: 73.0.3683.90
 - Fusion: FUSION_BA_3_10.0.5.013_M
 - BIOS: 5.04.42.0052-A-Z-017
 - Includes Microarchitectural Data Sampling fixes.
- SPR-36441 – Resolved an issue where unable to write on ATP SD Card.

6. CFE v3 Updates:

CFE-ET55-M-XX-032120-N-00-03.zip (Non-GMS)

- Updated below mentioned components:
 - Mx MF (8.2.4.8)
 - SPR34771 – Resolved an issue wherein sync was not proper while checking with access manager for permission with Mx component.
 - Bluetooth
 - SPR35735 – Resolved an issue where more than 7 HID devices were not connecting.
 - SPR36162 – Added Support for Dex
 - Zebra License Manager (3.1.1) has been included.
 - Data Analytics changes:
 - DataAnalytics has been renamed to Zebra Data Service.
 - DAInBuiltDCA has been renamed to Zebra Data Service Plugin.
 - SettingsEULA has been renamed to Zebra Data Services.
 - Cellular Manager (6.0.16)
 - Enhanced the Cellular data toggle UI to confirm the user confirmation on E4755 Modem devices.



Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	03-21-20.00-MN-U08-STD
Android Version	6.0.1
Security Patch level	2018-08-05 (Critical Patch Level: 2021-02-01)
Linux_kernel	3.14.55 (64-bit)
Component Versions	Please see Component Version under Addendum section

Important Links

<https://developer.zebra.com/>

<http://techdocs.zebra.com/>

support central

Installation and Setup instructions

[Installation and Setup instructions](#)

Device Support

This software release has been approved for Android ET55 M NonGMS models mentioned below.

Device	Operating System
ET55GE-L15E-00A6	Android 6.0.1
ET55GT-L15E-00A6	Android 6.0.1

ET55TE-L15E-00A6	Android 5.1.1, Android 6.0.1
ET55TT-L15E-00A6	Android 5.1.1, Android 6.0.1
ET55TE-L15E-00A6-EU	Android 5.1.1, Android 6.0.1
ET55TT-L15E-00A6-EU	Android 5.1.1, Android 6.0.1
ET55BE-L15E-00A6	Android 5.1.1, Android 6.0.1
ET55BE-L15E-00US	Android 5.1.1, Android 6.0.1
ET55BT-L15E-00A6	Android 5.1.1, Android 6.0.1
ET55BT-L15E-00US	Android 5.1.1, Android 6.0.1

Addendum

Component Version

Component / Description	Version
Android_SDK_Level	23
AppGallery	3.0.1.7
B2M_Elemez	1.0.0.347
BIOS version	5.04.42.0052-A-Z-017
Bluetooth stack	4.1
BT Firmware	BCM4354_003.001.012.0404.1391
Data_Analytics	1.0.2.1859
Datawedge	7.0.4
Device Patch Version	8
DWDemo	2.0.13
EMDK	7.0.0.2000
Enterprise Keyboard Manager ("added as a system application")	1.9.0.9



File Browser	1.19.1.5
License Manager	3.1.1
MXMF	8.2.5.12
NFC	8.1.24
OSX	INTL.60.6.7
Product Build Number	03-21-20.00-MN-U08-STD
RD Client	1.01.03
RxLogger	4.61.0.0
Scanner Firmware	PAABLC44-001-R01
Scanning_Framework	19.64.37.0
SOTI	13.3.0. Build 1059
StageNow	3.1.1.1019
Touch	2.2.AA
TXE FW	1.2.1.1153
ULPMC FW version	ULPMC_0065_08
Wi-Fi	FUSION_BA_3_10.0.5.017_M
WebView	87.0.4280.141

Revision History

Rev	Description	Date
1.0	Initial Release	Aug 07, 2020
2.0	CFEv7 Release	Nov 20, 2020
3.0	CFEv8 Release	Feb 04, 2021